



36IT Transmission Densitometer

Desktop Transmission Densitometer



The X-Rite® 36IT sets the standard in transmission densitometers. Thousands of desktop publishers, service bureaus, trade shops and printers rely on the 36IT to monitor the quality of their film output. It delivers unsurpassed versatility and accuracy. Whether you're using the 36IT for imagesetter linearization, exposure adjustment, processor quality control, or verifying duplicated or contacted films, you can be assured that you're getting the best possible results.

Versatility

The 36IT is the only densitometer to make accurate density and dot area measurements from your films. It was designed especially to allow instrument calibration to a known density reference *and* calibration to a known dot reference as well.

The 36IT is unique because it has a built-in UV response mode for measurement of otherwise invisible film base fog. An ordinary densitometer is not sensitive to UV blocking that can occur in the seemingly clear film base. The UV response of the 36IT can also be used to evaluate diazo films which are commonly used in the production of electronic circuit boards.

Automation Options

Using an RS232 interface you can record readings directly into a spreadsheet for quality control analysis. It is also possible to transmit data directly to your RIP to automate your calibration process.



Need More Functionality?

Combine the 361T transmission densitometer with one of our popular 500 Series Spectrodensitometers. Use these instruments in combination to create unique capabilities for black-and-white film and paper outputs.

This combination will give you all the tools you need to calibrate and control the variety of media used in the printing process: monitor film, proofs, press sheets, and paper outputs. What's more, this allows you to use both instruments at the same time, in separate locations.

Benefits:

- Extraordinary accuracy when measuring density functions. Able to measure densities exceeding 6.00D.
- Automates data entry into calibration software for imagesetter or platesetter systems.
- Sequence mode enables a consistent measurement procedure.
- High-contrast, adjustable display that is easy to see and easy to use.
- The most accurate industry dot area measurements, enabled by a separate calibration mode, ensures you are evaluating films properly.
- Can be combined with X-Rite 508 to measure solid and screened areas on both film and paper.
- Can be combined with X-Rite 518 Spectrodensitometer for monitoring color proofs, press sheets, films, and paper output.

Features:

- Includes X10 mode to measure density or dot sizes precisely.
- Directly measures negative and positive percent dot area.
- Includes 1mm, 2mm, and 3mm apertures allowing measurement of a variety of film line screen rulings. (0.5mm aperture optional.)
- Includes both Ortho and UV densitometer responses.
- Measuring range exceeds 6.00D.
- Includes both Ortho and UV densitometer responses.
- Conforms to ANSI PH2.19 and ISO 5/2 standards for transmission densitometry

Specifications:

Measuring Range

0 to >6.0D
0% to 100% (+/- dot)

Measuring Area

1mm, 2mm, and 3mm
(0.5mm optional)

Repeatability

Ortho, Visual
(2mm and 3mm aperture)
±0.01D (0.0D to 5.0D)
±2% (5.0D to 5.5D)
±3% (5.5D to 6.0D)

Ortho, Visual

(1mm aperture):
±0.01D (0.0D to 4.5D)
±1% (4.5D to 5.0D)

UV (3mm aperture)

±0.01D (0.0D to 3.5D)
±1% (3.5D to 4.0D)

Linearity

Ortho, Visual
(2mm and 3mm aperture)
±0.02D (0.0D to 5.0D)
±1% (5.0D to 5.5D)
±2% (5.5D to 6.0D)

Ortho, Visual

(1mm aperture)
±0.02D (0.0D to 4.5D)
±1% (4.5D to 5.0D)
UV (3mm aperture)
±0.02D (0.0D to 3.5D)
±1% (3.5D to 4.0D)

Warm-Up Time

2 minutes
5 minutes (UV)

Zero Stability

±0.02D per 8 hours

Response

X-Rite Ortho
X-Rite UV

Measuring Length (Throat)

10.25 inches

Operating

Temperature Range
50° to 104°F
(10° to 40°C)

Power Requirement

90-130 VAC 50-60 Hz
120-260 VAC 50-60 Hz
80 VA max.

Physical Dimensions

6.0" H (15.2 cm)
13.1" W (33.0 cm)
17.1" D (43.5 cm)

Weight

19 lbs. (8.63 kg)

Safety & Compliance

UL, CUL
CE
FCC Class A



xrite.com

ISO 9001
Certified

X-RITE WORLD HEADQUARTERS
Grandville, Michigan USA
(616) 534-7663
(800) 248-9748
FAX (616) 534-8960

X-RITE LATIN AMERICA
Hollywood, Florida USA
954-927-4979
FAX 954-927-4979

X-RITE LTD.
Poynton, Cheshire
United Kingdom
44 (0) 1625 871100
FAX 44 (0) 1625 871444

X-RITE MÉDITERRANÉE
Massy, France
33 1-6953-6620
FAX 33 1-6953-0052

X-RITE ITALY S.R.L.
Origgio (VA), Italy
(39) 02-967-34266
FAX (39) 02-967-30681

X-RITE GmbH
Köln, Germany
(49) 2203-91450
FAX (49) 2203-914519

Vyskov, Czech Republic
(00) 420 517-320-331
FAX (00) 420 517-320-335

**X-RITE INTERNATIONAL
TRADING LIMITED**
Shanghai, PR China
86-21-6427-2426
FAX 86-21-6427-5816

X-RITE ASIA PACIFIC LTD.
Quarry Bay, Hong Kong
(852) 2-568-6283
FAX (852) 2-885-8610

Tokyo, Japan
81-3-5439-5971
FAX 81-3-5439-5972

INFORMATION PROVIDED IN THIS DOCUMENT IS PROVIDED "AS IS" WITHOUT WARRANTY OF ANY KIND, EITHER EXPRESSED OR IMPLIED, INCLUDING BUT NOT LIMITED TO THE IMPLIED WARRANTIES OF MERCHANTABILITY AND/OR FITNESS FOR A PARTICULAR PURPOSE. The user assumes the entire risk as to the accuracy and the use of this information. All text must be copied without modification and all pages must be included. All components of this information must be distributed together. This

information may not be distributed for profit. © X-Rite, Incorporated 2003. X-Rite® is a registered trademark of X-Rite, Incorporated. Other brand and product names are trademarks of their respective holders. All trademarks may be registered in the United States and/or other countries. Product design and specifications subject to change without notice.

L11-010 (03/03) Printed in U.S.A.